

Safety Information

1. Safety information

- Please read carefully the Operation Manual before operating the instrument
- Don't cleanse the temperature measuring instrument with any solvent
- Safety symbols
 - Important notices against hazards
 - **CE** Compliant with European CE safety directive

This instrument complies with the standards provided below:

- EN61326-1
- EN60825-1

Warning!

Laser must be prevented from aligning itself towards human eyes or reflective surfaces.

2. Important notices

- When the working environment experiences a sudden change, the temperature measurement meter must be placed in an environment for 30 minutes. The measurement can be resumed only when the temperature inside the meter is consistent with that outside it.
- The electromagnetic field from electric welding and inductive heating must be minimized.





Measurement method

5. Measurement method

-

- 1. Set the upper limit value for alarms:
 - Press trigger + mode key to set the status for the instrument, switch Mode key to the upper limit set for an alarm. At this moment, the instrument's functional indication area shows HAL and secondary display panel the upper limit for an alarm. Press ▲/ ▼ key to increase or decrease alarm value. A long press on the ▲/▼ key will mean rapid increase or decrease in the set value.

The default alarm value for this instrument is 5°C.



 Set low alarm value for the instrument
 Press trigger + mode key to set the status for the instrument, switch Mode key to the low limit set for an alarm. At this moment, the instrument's

Measurement method

functional indication area shows HAL and secondary display panel the low limit for an alarm. Press $\blacktriangle/ \bigtriangledown$ key to increase or decrease alarm value. A long press on the $\blacktriangle / \blacktriangledown$ key will mean rapid increase or decrease in the set value. The default alarm value for this instrument is -5°C.



3. Set the emissivity for the instrument
Press trigger + mode key to set the emissivity for the instrument, switch Mode key to the low limit set for an alarm. At this moment, the instrument's functional indication area shows ^V^L_C and secondary display panel the emissivity for an alarm. Press ▲/
▼ key to increase or decrease emissivity value. A long press on the ▲/ ▼ key will mean rapid increase or decrease in the set value.



Measurement method

6. Turn on or off UVlight

Press () key to turn on or off UVlight. Leak detection:

The leakage of vehicle air conditioning and other high pressure systems can be detected quickly by ultraviolet.Fluorescent agent is injected into the air conditioning system, fluorescent agent will with the refrigerant in the air-conditioning system in circulation, when the air conditioning system has a leak, fluorescent agent will left the leakage.Fluorescence leakage under the irradiation of ultraviolet light can emit fluorescence at, and then find the leak.

7. Non-contact temperature measurement

Target the temperature measurement meter at an object and pull the trigger for a period to carry out continuous measurement of temperature. After display becomes stable, release the trigger to hold measurement results.



When the trigger is pressed, the instrument's secondary display panel will first show the set emissivity and then display the measured maximum temperature.



When the measured value is greater than ambient environment + HAL value or less than the ambient environment + LAL value, the red indicator of the instrument will be on to sound an alarm. Otherwise, the green indicator will be on.

8: K thermocouple temperature measurement After K type thermocouple probe is inserted into the thermocouple socket of the instrument, the instrument's functional indication area will display PRb and secondary display panel the temperature value of K thermocouple.







substances or oxidized surfaces of metals falls

TO

Emissivity

within the range of 0.85~0.98. The default emissivity of this measurement device is 0.95. The instrument's emissivity is set to be consistent with that of the object to be measured at the moment of measurement. The effect of emissivity on measurement result must be noticed at the time of measurement.

The diagram provided below is a reference table for emissivity. Table 2 Surface emissivity

Aluminum Metal	Ovidized	0.2.0.1
		0.2~0.4
	ASUUSAIIOyOxidized	0.3
	A3003AlloyRough	0.1~0.3
Brass	Polished	0.3
	Oxidized	0.5
Copper	Oxidized	0.4~0.8
	Electronic terminal	
	Board	0.6
Hastelloy		0.3~0.8
Chromium -Nickel-Iron Alloy	Oxidized	0.7~0.95
	Sandblast	0.3~0.6
	Electro-Polished	0.15
Iron	Oxidized	0.5~0.9
	Rusted	0.5~0.7

		Emissivity	
Iron(Cast)	Oxidized	0.6~0.95	
	No Oxidized	0.2	
	Melt & cast	0.2~0.3	
iron(Forged) Passivated	0.9	
Land	Rough	0.4	
Lead	Oxidized	0.2~0.6	
Mo Oxidized		0.2~0.6	
Nickel Oxid	ized	0.2~0.5	
Platinum Bla	ack	0.9	
	Cold rolled	0.7~0.9	
Steel	Sanding plate	0.4~0.6	
	Polished plate	0.1	
Zinc	Oxidized	0.1	
Asbestos		0.95	
Asphalt		0.95	
Basalt stone		0.7	
Carbon		0.8~0.9	
non-oxidized		0.7~0.8	
Graphite		0.9	
Silicon Carbide		0.95	
Clay		0.95	
Concrete		0.95	
Fabric		0.95	
Glass plate		0.85	

-

	Battery replacemen		
Sand-gravel	0.95		
Gypsum	0.8~0.95		
Ice	0.98		
Limestone	0.98		
Paper	0.95		
plastic	0.95		
Soil	0.9~0.98		
Water	0.93		
Wood (natural)	0.9~0.95		

8. Battery replacement When the battery's power is low, the battery symbol indicator 🗖 will be on. At such moment, you must replace the existing battery. What you need to do is to open the battery cover and replace the old battery with a new 9V battery. Refer to the diagram below:



100 M 100 M 100 M	And a state of the			75000000	100320302
000 2 ~ 7 65 6 8 6	9 F aller 8 6	S - 1- 1	and the	Y - L	1.377
009 8 44 49 5 5 5	法法 服用 化金属	8 87-1	80.00	12122	E
	infortune sales	a which	المشارقان	3.3.5.78	2 m 8m

9. Technical parameters

LCD	Color LCD	
D:S	12:1	
Emissivity	0.10~1.00 8~14um	
Response spectrum		
UV Light(BLUE)	~	
Laser	<1mW /630-670nm Level 2	
Response time	< 0.55	
Automatic shutdown	15 seconds	
Operational temperature	0~40 ℃	
Storage temperature	-10°C~60°C 9V 6F22 battery	
Power		
Measurement range (Non-contact temperature measurement)	-50°C~800°C (-58°F~1472°F)	
Precision (non-contact temperature measurement)	-50℃~0℃ ±3℃ 0~800℃ ± (1.5% reading +2℃ /4℃F)	
K type temperature measurement	-40°C~1000°C (-40°F~1832°F) ±(1.5% reading+2°C/4°F)	